

## Bridge collapses



### Overview

On March 26, 2024, the main spans and the three nearest northeast approach spans of the Francis Scott Key Bridge across the Patapsco River in the Baltimore metropolitan area of Maryland, United States, collapsed after one of the bridge piers was struck by the container ship Dali, which had suffered catastrophic power outages that impaired its control systems. Six members of a maintenanc. Date March 26, 2024 Time 1:28:49 a.m. (05:28:49 ) Location, Maryland, United States Type Bridge collapse Background The was a arch-shaped, the second-longest in the United States and. Opened in 1977, the 1.6-mile (2.6 km; 1.4 nmi) bridge ran northeast fr. Dali left the Port of Baltimore at 12:44 a.m. (04:44 ) on Tuesday, March 26, 2024, bound for, Sri Lanka. The ship had two local on board. Following standard operating procedure in Baltimore. NOAA reported a water temperature of 47 °F (8 °C) at the time of the collapse. Two people were rescued, one from the river in "very serious" condition and the other from the remaining bridge, uninjured. One of thos.

## Bridge collapses



The National Transportation Safety Board (NTSB) released its final report more than 20 months after the deadly collapse of Baltimore's Francis Scott Key Bridge. Investigators concluded ...



The popular bridge in Traverse City was overtaken by dangerous flooding as the Boardman River surged over the bridge barrier, submerged the roadway and eventually destroyed it ...



The latest on the Francis Scott Key Bridge collapse in Baltimore, Maryland. What we know about the victims, recovery effort, port reopening and more.



The Northern Village of Pinehouse's road access to southern Saskatchewan is temporarily cut off after the collapse of a bridge and a separate highway closure caused by flooding.



Federal investigators called the deadly 2024 collapse of the Francis Scott Key Bridge in Baltimore "preventable" and recommended closer inspections.



A section of Bhagalpur's Vikramshila Bridge collapsed into the Ganga River. Traffic is suspended between North and South Bihar. Read the latest updates here.



A substantial portion of the bridge subsequently collapsed into the river, and portions of the pier, deck and truss spans collapsed onto the vessel's bow and forwardmost container bays. A ...



Under-construction bridge collapses in Oconomowoc In Oconomowoc, a street bridge caved in, sending concrete into the Oconomowoc river. This is the bridge's second structural issue in ...



A misplaced wire label, the vulnerability of a bridge and other mishaps in protocols likely caused the collapse of Baltimore's Francis Scott Key ...



On March 26, 2024, the main spans and the three nearest northeast approach spans of the Francis Scott Key Bridge across the Patapsco River in the Baltimore metropolitan area of Maryland, United ...



A misplaced wire label, the vulnerability of a bridge and other mishaps in protocols likely caused the collapse of Baltimore's Francis Scott Key Bridge after a large vessel struck it in the...

## Contact Us

For more information, pricing, or custom energy solutions, please contact us:

Website: <https://www.gdroofing.co.za>

Email: [sales@gdroofing.co.za](mailto:sales@gdroofing.co.za)

Phone: +27 72 418 9365

Address: 22 Electron Avenue, Isando, Johannesburg, 1600, South Africa

This document is for informational purposes only. Specifications subject to change without notice.

